

SSME EA/CIL
REDUNDANCY SCREEN

Component Group: Joints
CIL Item: L103A-01
Part Number: See Table L103A
Component: Hot Gas System Joints
FMEA Item: L103A
Failure Mode: Leakage.

Prepared: D. Early
Approved: T. Nguyen
Approval Date: 7/25/00
Change #: 1
Directive #: CCBDEME3-01-5638

Page: 1 of 1

| Phase | Failure / Effect Description | Criticality Hazard Reference |
|-----------|--|---------------------------------|
| SM 4.1 | Hot gas leakage into aft compartment. Aft compartment overpressurization. Possible fire or detonation. Loss of vehicle. Redundancy Screens: SINGLE POINT FAILURE: N/A | 1 ME-D3S,A,M,C |

SSME FMEA/CIL
DESIGN

Component Group: Joints
CIL Item: L103A-01
Part Number: See Table L103A
Component: Hot Gas System Joints
FMEA Item: L103A
Failure Mode: Leakage.

Prepared: D. Early
Approved: T. Nguyen
Approval Date: 7/25/00
Change #: 1
Directive #: CCBD ME3-01-5638

Page: 1 of 2

Design / Document Reference

FAILURE CAUSE: A: Seal failure.

ALL THE HOT GAS JOINTS NOTED IN THE FMEA USE PRESSURE-ASSISTED SEALS. THE PRESSURE-ASSISTED SEALS, EXCEPT FOR THE BELLOWS SEAL, ARE A VARIATION OF A "U" SHAPE CROSS-SECTION SEAL RING (1). THE SEALS ARE COMPRESSED DURING THE JOINT ASSEMBLY, WHICH PROVIDES A LOAD AT THE SEAL TIPS TO PROVIDE SEALING CAPABILITY AT LOW PRESSURES. AS THE PRESSURE INCREASES, IT ACTS ON THE "U" SHAPE AND INCREASES THE LOAD TO THE SEAL TIPS AND PROVIDES SEALING CAPABILITY AT THE HIGH SYSTEM PRESSURES. THE COMBINATION OF THE INSTALLATION DEFLECTION AND THE PRESSURE INSIDE OF THE "U" SHAPE PERMITS THE SEALING TIP TO COMPENSATE FOR THE JOINT SEPARATION UNDER SYSTEM PRESSURE. THESE INTERACTIONS PROVIDE FOR LEAK FREE JOINTS. THE SEAL MATERIAL IS INCONEL 718. THIS ALLOY IS USED FOR ITS STRENGTH, HEAT TREATABILITY, AND ABILITY TO RETAIN ITS STRENGTH AT BOTH CRYOGENIC AND ELEVATED TEMPERATURES (2). THE SEALS ARE PLATED TO PROVIDE A DUCTILE LOW YIELD STRENGTH MATERIAL ON THE SEAL TIP SO THE SEAL WILL CONFORM TO THE SURFACE TOPOGRAPHY ON THE MATING FLANGES. THE RD261-3014 AND RD261-3017 (VARIOUS SIZES) SEALS ARE MADE OF INCONEL 718 AND ARE USED IN JOINTS WITH SERVICE TEMPERATURE REQUIREMENTS FROM -423 DEGREES F TO 1000 DEGREES F, AND PRESSURES UP TO 8,000 PSIG. THEY ARE SILVER PLATED WITH AN INITIAL GOLD UNDERCOAT. THE GOLD UNDERCOAT PREVENTS OXIDATION OF THE SUBSTRATE AT TEMPERATURES ABOVE 600 DEGREES F, AND THUS PREVENTS BLISTERING OF THE SILVER PLATING. SILVER IS USED DUE TO ITS LOW YIELD STRENGTH AND DUCTILITY REQUIRED FOR EFFECTING A SEAL, AND ITS CORROSION RESISTANCE (2). RD261-3016 AND RD261-3019 SEALS ARE SIMILAR TO THE RD261-3017 SEALS EXCEPT THEY HAVE A RHODIUM OVERPLATE ON THE SILVER PLATING TO PREVENT THE BONDING OF THE SILVER TO THE MATING FLANGE SURFACE AT TEMPERATURES ABOVE 1000 DEGREES F (2). SILVER PLATING PROVIDES PROTECTION FROM HYDROGEN ENVIRONMENT EFFECTS (2). SEALS REMOVED FROM BROKEN JOINTS ARE EITHER REPLACED OR ARE REINSPECTED AND REUSED. GENERAL GUIDELINES ARE TO REPLACE SEALS AT ALL STRETCH JOINTS AND OTHER HARD-TO-GET-AT JOINT SEALS. NON-STRETCH JOINT SEALS WITH EASY ACCESS ARE REINSPECTED AND REUSED IF FOUND ACCEPTABLE (3).

THE RD261-3016 SEAL, WHICH IS SIMILAR TO THE RD261-3017 AND RD261-3019 SEALS, WAS DVS TESTED IN A SIMULATED ENGINE JOINT AT A HIGH TEMPERATURE. THE SEALS MET LEAKAGE REQUIREMENTS WHILE THE PRESSURE WAS CYCLED FROM AMBIENT TO 5,000 PSIG FOR 240 CYCLES (4). IN ADDITION TO THE ABOVE TESTS, SEALS HAVE BEEN SUBJECTED TO STRUCTURAL VERIFICATION AT PRESSURES UP TO TWICE OPERATING PRESSURE. AFTER COMPLETION OF 240 PRESSURE CYCLES, THE SEALS STILL MET THE LEAKAGE REQUIREMENT (5). HIGH CYCLE AND LOW CYCLE FATIGUE LIFE OF THE HOT GAS SEALS MEET CEI REQUIREMENTS (8). THE MINIMUM FACTORS OF SAFETY FOR THE SEALS MEET CEI REQUIREMENTS (9). THE SEALS PARENT MATERIALS WERE CLEARED FOR FRACTURE MECHANICS/NDE FLAW GROWTH SINCE THEY ARE NOT FRACTURE CRITICAL PARTS (10). THE FMEA/CIL WELDS ARE CLEARED FOR FRACTURE MECHANICS/NDE FLAW GROWTH BY THE WELD ASSESSMENT (11). TABLE L103A LISTS ALL FMEA/CIL WELDS AND IDENTIFIES THOSE WELDS IN WHICH CRITICAL INITIAL FLAW SIZE IS NOT DETECTABLE AND THOSE WELDS IN WHICH THE ROOT SIDE IS NOT ACCESSIBLE FOR INSPECTION. THOSE WELDS IN WHICH THE CRITICAL INITIAL FLAW SIZE IS NOT DETECTABLE ARE ACCEPTABLE FOR FLIGHT BY RISK ASSESSMENT (11). SPECIAL PACKAGING REQUIREMENTS ARE SPECIFIED TO PROTECT THE SEALS DURING SHIPMENT OR STORAGE (12).

THE FLANGES ARE DESIGNED TO INTERFACE WITH THE SEAL AND HAVE THE NECESSARY FEATURES TO PROVIDE A LEAK FREE JOINT. THE FLANGE DESIGN SPECIFIES THE REQUIREMENTS FOR SURFACE FLATNESS, SURFACE FINISH, AND THE SEALING SURFACE AREA ON THE FLANGE. THIS ENSURES THAT THE SEAL MATING AREA IS CLOSELY INSPECTED TO VERIFY IT IS FREE OF DEFECTS WHICH WOULD CAUSE LEAKAGE. TYPICALLY, ONE FLANGE HAS A SEAL GROOVE FOR POSITIONING THE SEAL WHILE THE OTHER FLANGE IS FLAT. BOLT HOLE CLEARANCES ARE CONTROLLED BY THE FLANGE DESIGN TO PREVENT EXCESSIVE LATERAL MOTION WITHIN THE JOINT. THE FLANGE DESIGN ALSO CONTROLS THE DEFLECTION IN BOTH THE RADIAL AND CIRCUMFERENTIAL DIRECTIONS. RADIAL DEFLECTIONS ARE LARGELY CONTROLLED BY THE THICKNESS OF THE FLANGE WHILE CIRCUMFERENTIAL DEFLECTIONS ARE CONTROLLED BY FLANGE THICKNESS AND BOLTING REQUIREMENTS. THE JOINT DESIGNS HAVE CLOSE BOLT SPACING TO PREVENT UNACCEPTABLE FLANGE BOWING (DEFLECTION) BETWEEN BOLTS. TYPICAL FLANGES WERE USED DURING DVS STATIC SEAL TESTING WHICH CONFIRMED DESIGN REQUIREMENTS ON THE ENGINE FLANGES (4) (5) (13). LEAK CHECKS DURING ENGINE BUILD AND AT INTERVALS DURING ENGINE SERVICE HAVE SHOWN THAT THE FLANGES PERFORM SATISFACTORILY AND MAINTAIN JOINT INTEGRITY. THIS HAS BEEN FURTHER DEMONSTRATED BY THE FLANGES ON TWO HIGH TIME ENGINES: ENGINE 2010 WITH 65 STARTS AND 19,903 SECONDS OF HOT FIRE TIME (6), AND ENGINE 2014 WITH 70 STARTS AND 19,102 SECONDS OF HOT FIRE TIME (7).

(1) RD261-3014, RD261-3016, RD261-3017, RD261-3019; (2) RSS-8582; (3) SEE TABLE 103A-CIL; (4) RSS-514-12; (5) RSS-514-6; (6) 529-143-IL-85-0126; (7) SSME-86-00096; (8) RL00532, CP320R0003B; (9) RSS-8546; (10) NASA TASK 117; (11) RSS-8756; (12) RA0116-082; (13) RSS-514-16

Component: Joints
CIL Item: L103A-01
Part Number: See Table L103A
Component: Hot Gas System Joints
FMEA Item: L103A
Failure Mode: Leakage.

Prepared: D. Early
Approved: T. Nguyen
Approval Date: 7/25/00
Change #: 1
Directive #: CCBD ME3-01-5638

Page: 2 of 2

Design / Document Reference

FAILURE CAUSE: B: Loss of bolt preload.

JOINT BOLTING IS AN INTEGRAL PART OF STATIC SEAL JOINTS. THE BOLTING IS DESIGNED TO TAKE INTO CONSIDERATION BOTH THE PRESSURE SEPARATING LOAD AND ALL EXTERNAL LOADS THAT ACT ON THE JOINT. BOLTS ARE SPACED CLOSE TOGETHER TO MINIMIZE FLANGE DEFLECTION. HIGH STRENGTH BOLTS ARE USED TO PROVIDE THE NECESSARY CLAMPING LOAD WHILE KEEPING THE TOTAL JOINT WEIGHT TO A MINIMUM. THE BOLT BASE MATERIALS ARE A-286 AND INCONEL 718, WHICH ARE USED FOR THEIR STRENGTH, ELASTIC MODULUS, AND COMPATIBILITY WITH ENGINE ENVIRONMENT (1) TEMPERATURES. THE BOLTS OR NUTS ARE NORMALLY COATED WITH DRY-FILM LUBRICANTS OR PLATED TO REDUCE THE TORQUE REQUIRED FOR TIGHTENING AND TO REDUCE THE LOAD RANGE VARIATIONS DUE TO FRICTION. THE FASTENERS (BOLTS AND STUDS) MAY BE INSTALLED INTO THREADED HOLES OR IN NUTS. THE BOLTS ARE LOCKWIRED TO PREVENT BOLT BACKOFF ON THREADED HOLE INSTALLATIONS AND THE NUTS HAVE SELF-LOCKING, DEFORMED THREADS OR PRELOAD LOCKING THREAD FORMS, TO PREVENT NUT BACKOFF ON BOLT-NUT INSTALLATIONS. FASTENER INSTALLATION IS CONTROLLED AT ENGINE ASSEMBLY TO ENSURE THAT THE INSTALLATION HAS THE PROPER BOLT LOADING AND NO DAMAGE OCCURS TO EITHER THE FASTENERS OR FLANGES. ON TORQUED INSTALLATIONS THE TORQUE IS APPLIED IN THREE EQUAL STEPS WITH TORQUE AT EACH STEP APPLIED IN A CROSS TORQUEING PROCEDURE (2). ON HIGH PRESSURE JOINT INSTALLATIONS, THE FASTENERS (BOLTS AND STUDS) ARE STRETCHED TO A DRAWING SPECIFIED ELONGATION. THIS OPERATION IS CONTROLLED BY A SPECIFICATION (3) WHICH REQUIRES AN INITIAL TORQUE TO BE APPLIED IN A CROSS TORQUEING PROCEDURE. THE FASTENERS ARE THEN STRETCHED TO A FINAL ELONGATION USING A SPECIAL MACHINE (EXTENSOMETER) AND USING A CROSS TORQUEING PROCEDURE. THE STRETCHING PROCEDURES ARE PERFORMED BY TRAINED AND CERTIFIED PERSONNEL AND WITNESSED BY A CERTIFIED INSPECTOR. BOLTS ARE REQUIRED TO BE LOCKWIRED AFTER INSTALLATION (2)(3). REUSE OF A FASTENER REQUIRES RELUBRICATION AND INSPECTION FOR GALLING, THREAD DAMAGE, OR WRENCHING ELEMENT DISTORTION. ALL SELF-LOCKING NUTS REQUIRE VERIFICATION OF THE LOCKING FEATURE DURING NUT INSTALLATION (2)(3). THE MATERIALS USED FOR THE WASHERS IN THE JOINT BOLTING ARE SELECTED FOR THEIR COMPRESSIVE YIELD STRENGTH TO PREVENT YIELDING UNDER JOINT OPERATING PRESSURES (1). THE STRETCH FASTENERS WERE USED THROUGHOUT THE STATIC SEAL DVS TESTING ON SIMULATED JOINTS WHICH DEMONSTRATED THE BOLTING DESIGN APPROACH AND THE ABILITY OF THE JOINTS TO MEET THE LEAKAGE REQUIREMENTS (4). LEAK CHECKS DURING ENGINE BUILD AND AT INTERVALS DURING ENGINE SERVICE HAVE SHOWN THAT JOINT INTEGRITY IS SATISFACTORILY MAINTAINED BY THE BOLTING DESIGNS.

(1) RSS-8582; (2) RA0101-002; (3) RL00114; (4) RSS-514-16, RSS-514-12, RSS-514-6

**SSME FMEA/CIL
INSPECTION AND TEST**

Component Group: Joints
 CIL Item: L103A-01
 Part Number: See Table L103A
 Component: Hot Gas System Joints
 FMEA Item: L103A
 Failure Mode: Leakage.

Prepared: D. Early
 Approved: T. Nguyen
 Approval Date: 7/25/00
 Change #: 1
 Directive #: CCBD ME3-01-5638

Page: 1 of 2

| Failure Causes | Significant Characteristics | Inspection(s) / Test(s) | Document Reference |
|---|----------------------------------|---|--|
| A | SEAL-P/A | | RD261-3014 |
| | SEAL-P/A | | RD261-3016 |
| | SEAL-P/A | | RD261-3017 |
| | SEAL-P/A | | RD261-3019 |
| | MATERIAL INTEGRITY | MATERIAL INTEGRITY IS VERIFIED PER DRAWING REQUIREMENTS. | RD261-3014 RD261-3016 RD261-3017 RD261-3019 |
| | | TUBING WELDS ON MATERIALS USED TO FABRICATE SEALS ARE INSPECTED PER SPECIFICATION REQUIREMENTS INCLUDING X-RAY AND PENETRANT INSPECTIONS. | RF0004-301 RL10011 |
| | | HEAT TREAT OF SEALS IS VERIFIED PER DRAWING REQUIREMENTS. | RD261-3014 RD261-3016 RD261-3017 RD261-3019 |
| | | SEALS ARE PENETRANT INSPECTED PER DRAWING REQUIREMENTS. | RD261-3014 RD261-3016 RD261-3017 RD261-3019 |
| | PLATING INTEGRITY | SEAL PLATING IS VERIFIED PER DRAWING AND SPECIFICATION REQUIREMENTS. | RD261-3014 RD261-3016 RD261-3017 RD261-3019 RA1609-006 RA1609-001 |
| | SURFACE FINISH | SEAL SURFACE FINISHES ARE VERIFIED PER DRAWING REQUIREMENTS. | RD261-3014 RD261-3016 RD261-3017 RD261-3019 |
| | CLEANLINESS | SEALS ARE VERIFIED TO BE CLEAN TO PROPELLANT SERVICE LEVEL PER DRAWING REQUIREMENTS. | RD261-3017 RD261-3019 |
| | FLANGE SEALING SURFACE INTEGRITY | ALL FLANGE SEALING SURFACES ARE INSPECTED FOR SURFACE FINISH, WIDTH, AND LOCATION PER DRAWING REQUIREMENTS. | SEE TABLE L103A-CIL. |
| SEAL GROOVE DIMENSIONS ARE VERIFIED ON APPLICABLE JOINT FLANGES PER DRAWING REQUIREMENTS. | | SEE TABLE L103A-CIL. | |

Component Group: Joints
 CIL Item: L103A-01
 Part Number: See Table L103A
 Component: Hot Gas System Joints
 FMEA Item: L103A
 Failure Mode: Leakage.

Prepared: D. Earl
 Approved: T. Nguy
 Approval Date: 7/25/00
 Change #: 1
 Directive #: CCBD ME3-01-5638

Page: 2 of 2

| Failure Causes | Significant Characteristics | Inspection(s) / Test(s) | Document Reference |
|----------------|---|--|---|
| B | BOLT BOLT BOLT BOLT NUT NUT NUT STUD BOLT PRELOAD | BOLT AND NUT FINAL TORQUES ARE VERIFIED PER DRAWING REQUIREMENTS. STRETCH BOLT AND STUD LENGTHS ARE INSPECTED PRIOR TO INSTALLATION PER DRAWING REQUIREMENTS. FINAL STRETCH BOLT AND STUD LENGTHS ARE VERIFIED PER DRAWING REQUIREMENTS. PROPER LOCK WIRING OF BOLTS IS VERIFIED. NEW SELF-LOCKING NUTS ARE LOT SAMPLE ACCEPTANCE TESTED TO ASSURE BREAK AWAY TORQUES AND LOCKING FEATURES ARE MAINTAINED AFTER MULTIPLE INSTALLATION AND REMOVAL CYCLES. | MS21280 RD111-4101 RD111-4102 RD111-4105 RD114-8010 RD114-8011 RD114-1019 RE113-3003 SEE TABLE L103A-CIL. SEE TABLE L103A-CIL. SEE TABLE L103A-CIL. SEE TABLE L103A-CIL. RB0170-156 RD114-8010 |
| | BOLT LUBRICATION | BOLT DRY-FILM LUBRICATION IS VERIFIED PER DRAWING REQUIREMENTS. | RD111-4101 RD111-4102 RD111-4105 RE113-3003 |
| | NUT LUBRICATION | NUT DRY-FILM LUBRICATION IS VERIFIED PER DRAWING REQUIREMENTS. SILVER PLATING ON NOTED NUT IS INSPECTED. | RD114-8010 RD114-8011 RD114-1019 |
| ALL CAUSES | LEAK TESTS | THE ENGINE ASSEMBLY ABOVE THE HEAT SHIELD IS BAGGED AND HELIUM LEAK TESTED, WHICH VERIFIES ADEQUATE JOINT SEALING. ALL JOINTS ARE LEAK TESTED PRIOR TO HOT FIRE. ALL INTERCONNECT JOINTS ARE LEAK TESTED AFTER HOT FIRE. JOINTS ARE LEAK TESTED WHENEVER DISTURBED. THE NOTED HOT GAS JOINTS WITHIN THE AFT COMPARTMENT (EXCEPT INSTRUMENTATION JOINTS) ARE SIGNATURE LEAK TESTED PRIOR TO EACH FLIGHT. CONTINGENCY REQUIREMENTS FOR VIOLATED PROPELLANT JOINTS, AFTER SIGNATURE LEAK TEST, WITH 4 FASTENERS OR LESS ARE BUBBLE SOAP AND MASS SPECTROMETER LEAK TESTED PRIOR TO EACH FLIGHT. (LAST TEST) | RL00712 RL00050-04 RL00056-06 RL00056-07 OMRSD V41GEN.565 OMRSD S00000.950 OMRSD V41GEN.565 MF0001-003 |

Failure History: Comprehensive failure history data is maintained in the Problem Reporting database (PRAMS/PRACA)
 Reference: NASA letter SA21/88/308 and Rocketdyne letter 88RC09761.
 Operational Use: Not Applicable.

SSME FMEA/CIL
CIL SYSTEM JOINTS

Component Group: Joints
Item Name: Hot Gas System Joints
Item Number: L103A

Prepared: D. Early
Approved: T. Nguyen
Approval Date: 7/25/00
Change #: 1
Directive #: CCBDM E3-01-5638
Page: 1 of 2

| Joint | Location | Seal Part Number | Seal Part Number Description | Torque or Stretch | Locking Feature | Assembly Drawing |
|--------|--|------------------|---|-------------------|-----------------|------------------|
| D1 | HPOTP RS007701 TO HPOTP TURBINE PRIMARY SEAL DRAIN MANIFOLD RS007118 | RD261-3014 | PRESSURE ACTUATED - SILVER PLATE OVER GOLD OVER INCO 718 | TORQUE | LOCKWIRE | RS007006 |
| D2 | HPOTP RS007701 TO HPOTP SECONDARY SEAL DRAIN LINE RS007111 | RD261-3014 | PRESSURE ACTUATED - SILVER PLATE OVER GOLD OVER INCO 718 | TORQUE | LOCKWIRE | RS007006 |
| D25 | HPOTP TURBINE PRIMARY SEAL DRAIN MANIFOLD RS007118 TO OVERBOARD LINE | RD261-3014 | PRESSURE ACTUATED - SILVER PLATE OVER GOLD OVER INCO 718 | TORQUE | LOCKNUT | RS007006 |
| D26 | HPOTP SECONDARY SEAL DRAIN LINE RS007111 TO OVERBOARD LINE | RD261-3014 | PRESSURE ACTUATED - SILVER PLATE OVER GOLD OVER INCO 718 | TORQUE | LOCKNUT | RS007006 |
| D35.1 | HPOTP SECONDARY SEAL CAVITY TRANSDUCER LINE R0011628 TO HPOTP SECONDARY SEAL CAVITY RS007701 | RD261-3017 | PRESSURE ACTUATED - SILVER PLATE OVER GOLD OVER INCO 718 | TORQUE | LOCKWIRE | RS007007 |
| D35.2 | HPOTP SECONDARY SEAL CAVITY TRANSDUCER LINE R0011628 TO HPOTP SECONDARY SEAL CAVITY PRESSURE TRANSDUCER RES7001/RE2233 | RD261-3017 | PRESSURE ACTUATED - SILVER PLATE OVER GOLD OVER INCO 718 | TORQUE | LOCKNUT | RS007007 |
| G1 | OXIDIZER PREBURNER RS009007 TO BOSS RS009557 PLUG | RD261-3019 | PRESSURE ACTUATED - RHODIUM PLATE OVER SILVER OVER GOLD OVER INCO 718 | TORQUE | LOCKWIRE | RS007002 |
| G1.1 | OXIDIZER PREBURNER RS009007 TO BOSS RS009557 PLUG | RD261-3019 | PRESSURE ACTUATED - RHODIUM PLATE OVER SILVER OVER GOLD OVER INCO 718 | TORQUE | LOCKWIRE | RS007002 |
| G1.3 | OXIDIZER PREBURNER RS009007 TO BOSS RS009528 PLUG | RD261-3019 | PRESSURE ACTUATED - RHODIUM PLATE OVER SILVER OVER GOLD OVER INCO 718 | TORQUE | LOCKWIRE | RS007002 |
| G3.1 | POWERHEAD RS007010 TO HPOTP TURBINE DISCHARGE TEMPERATURE TRANSDUCER RES7004 | RD261-3019 | PRESSURE ACTUATED - RHODIUM PLATE OVER SILVER OVER GOLD OVER INCO 718 | TORQUE | LOCKWIRE | RS007007 |
| G3.2 | POWERHEAD RS007010 TO HPOTP TURBINE DISCHARGE TEMPERATURE TRANSDUCER RES7004 | RD261-3019 | PRESSURE ACTUATED - RHODIUM PLATE OVER SILVER OVER GOLD OVER INCO 718 | TORQUE | LOCKWIRE | RS007007 |
| G4.1 | FUEL PREBURNER RS009023 TO FPB CHAMBER PRESSURE TRANSDUCER MOUNT R0014416 | RD261-3019 | PRESSURE ACTUATED - RHODIUM PLATE OVER SILVER OVER GOLD OVER INCO 718 | TORQUE | LOCKWIRE | RS007007 |
| G4.1.1 | FUEL PREBURNER CHAMBER PRESSURE TRANSDUCER RES7001/RE2233 TO MOUNT R0014416 | RD261-3019 | PRESSURE ACTUATED - RHODIUM PLATE OVER SILVER OVER GOLD OVER INCO 718 | TORQUE | LOCKWIRE | RS007007 |

* Unnumbered Component Joint

Component Group: Joints
Item Name: Hot Gas System Joints
Item Number: L103A

Prepared: D. Early
Approved: T. Nguy
Approval Date: 7/25/00
Change #: 1
Directive #: CCBD ME3-01-5638
Page: 2 of 2

| Joint | Location | Seal Part Number | Seal Part Number Description | Torque or Stretch | Locking Feature | Assembly Drawing |
|--------|--|------------------|--|-------------------|-----------------|------------------|
| G4.3 | FUEL PREBURNER RS009023 TO BOSS R0011042 PLUG | RD261-3019 | PRESSURE ACTUATED - RHODIUM PLATE OVER SILVER OVER GOLD OVER INCO 718 | TORQUE | LOCKWIRE | RS007002 |
| G5.1 | POWERHEAD RS007010 TO HPFTP TURBINE DISCHARGE TEMPERATURE TRANSDUCER RES7004 | RD261-3019 | PRESSURE ACTUATED - RHODIUM PLATE OVER SILVER OVER GOLD OVER INCO 718 | TORQUE | LOCKWIRE | RS007007 |
| G5.2 | POWERHEAD RS007010 TO HPFTP TURBINE DISCHARGE TEMPERATURE TRANSDUCER RES7004 | RD261-3019 | PRESSURE ACTUATED - RHODIUM PLATE OVER SILVER OVER GOLD OVER INCO 718 | TORQUE | LOCKWIRE | RS007007 |
| G6 | POWERHEAD RS007010 TO HPFTP RS007501 | RD261-3016 | PRESSURE ACTUATED - RHODIUM PLATE OVER SILVER OVER GOLD OVER INCO 718. | STRETCH | LOCK NUT | RS007002 |
| G7 | POWERHEAD RS007010 TO INJECTOR BOSS RS007167 PLATE | RD261-3019 | PRESSURE ACTUATED - RHODIUM PLATE OVER SILVER OVER GOLD OVER INCO 718 | TORQUE | LOCKWIRE | RS007002 |
| G7.2 | POWERHEAD RS007010 TO MCC FUEL INJECTOR PRESSURE TRANSDUCER MOUNT RS007371 | RD261-3019 | PRESSURE ACTUATED - RHODIUM PLATE OVER SILVER OVER GOLD OVER INCO 718 | TORQUE | LOCKWIRE | RS007007 |
| G7.2.1 | MCC FUEL INJECTOR PRESSURE TRANSDUCER RES7001 TO MOUNT RS007371 | RD261-3019 | PRESSURE ACTUATED - RHODIUM PLATE OVER SILVER OVER GOLD OVER INCO 718 | TORQUE | LOCKWIRE | RS007007 |
| N14 | PLATE R0019584 TO HPOTP TURBINE SHAFT COOLANT PASSAGE PURGE PORT RS007729 | RD261-3017 | PRESSURE ACTUATED - SILVER PLATE OVER GOLD OVER INCO 718 | TORQUE | LOCKWIRE | RS007005 |

SSME FMEA/CIL
WELD JOINTS

Component Group: Joints
CIL Item: L103A
Part Number: See Table L103A
Component: Hot Gas System Joints
FMEA Item: L103A

Prepared: D. Early
Approved: T. Nguyen
Approval Date: 7/25/00
Change #: 1
Directive #: CCBD ME3-01-5638
Page: 1 of 1

| Component | Basic Part Number | Weld Number | Weld Type | Class | Root Side Not Access | Critical Initial Flaw Size Not Detectable | | Comments |
|-----------|-------------------|-------------|-----------|-------|----------------------------|---|-----|----------|
| | | | | | | HCF | LCF | |
| SEAL | RD261-3016 | 1 | GTAW | I | | | | |
