

Document No: 18901-70131B
 Release Date: 10/30/95
 Revision Date: 02/26/96
 Page A-25

Failure Modes and Effects Analysis/Critical Items List

FMEA No:	OSS-ST576-12	Originator:	G. Hall/OSS	Project:	STS-76 DTO 671
Part Name:	Hook, Large	ORU Part #	SED33107201-301	Quantity:	1
Part #:	SED33108378-501	ORU Part Name:	Safety Tether Assy	System:	EVA
Drawing:	SED33108378	Subsystem:	N/A	Effectivity:	STS-76
Time to Effect:	N/A				
Time to Detect:	N/A				
Time to Correct:	N/A				
Failure Detection/Flight:	N/A				

Remarks:

-Retention Rationale-

(A) Design:	N/A
(B) Test:	N/A
(C) Inspection:	N/A
(D) Failure History:	N/A
(E) Operational Use:	N/A

Prepared By:	G. Hall/OSS	Revision:	B	Date:	02/26/96
--------------	-------------	-----------	---	-------	----------